

Certificate No.: GLIS/IN/SAFE/2023/08/CC-4748

GL Ref. No.: 101-091-3202-08-0815

CERTIFICATE

This is to certify that The Product(s)

Pneumatic Rack and Pinion Actuators

Manufactured by,

M-tor Q Controls India

B-3, E-10, 19(3) General Block, MIDC, Bhosari, Pune-411026, Maharashtra, India.

Models: Series MTSR and MTDA

has been reviewed / assessed with respect to Functional Safety Standards

IEC 61508 : 2010 Parts 1-7

Systematic capability: SC 2 (SIL-2 Capable)

Random capability: Type A, Route 1_H Device

(PFH/PFD_{AVG} and Architecture Constraints must be verified for each application)

Date of Issue: August 12, 2023

Valid up to : August 11, 2026

This Certificate of Conformity issued under ISO/IEC 17065 for Product Certification Body accredited by SIAC(E) (Swiss International Accreditation Center - EUROPE). Accreditation No.1120

Issued at: Local HO

Ahmedabad, India

12.08.2023

Head - Tech. Certification

H.O.(INDIA): Gulf Lloyds Industrial Services (INDIA) Pvt. Ltd.) 910, GALA Empire, Drive-in Road, Ahmedabad-380054, Gujarat, India. info@guffloyds.org; certification@guffloyds.org H.Q.(UAE): Gulf Lloyds (Middle-East) LLC P.O. Box-30765, Electra Street Abu Dhabi, UAE; uae@guiflloyds.org;

www.gulflloyds.org

الخليج لويدز (الشرق الأوسط)

DOC. NO.:GL/TTC/009





Certificate No.: GLIS/IN/SAFE/2023/08/CC-4748

GL Ref. No.: 101-091-3202-08-0815

PRODUCTS COVERED BY THIS CERTIFICATE

Product Name	Туре	Design pressure (in bar)	(in mm)	Temp. (in °C)	Fluid Group /Type	
Pneumatic Rack and Pinion Double acting actuator	MTDA-032, MTDA-040, MTDA-050, MTDA-060, MTDA-075, MTDA-085, MTDA-095, MTDA-105, MTDA-125, MTDA-140, MTDA-160, MTDA-190, MTDA-210, MTDA-240, MTDA-270, MTDA-300, MTDA-350	10.5	32mm to 350mm	(-50 to +80)	Air / Gr II	
Pneumtaic Rack and Pinion Spring return actuator	MTSR-040, MTSR-050, MTSR-060, MTSR-075, MTSR-085, MTSR-095, MTSR-105, MTSR-125, MTSR-140, MTSR-160, MTSR-190, MTSR-210, MTSR-240, MTSR-270, MTSR-300, MTSR-350	10.5	40mm to 350mm	(-50 to +80)	Air / Gr II	

Note: The above mentioned models and any sub models of these actuators are all covered by this Certificate

Random failure rates					
Configuration	Safety function	λου [1/h]	λοο [1/H]	λ _s [1/H]	
M-torQ series MTSR spring return - No PST	1	1,57E-08	0,00E+00	0,00E+00	
M-torQ series MTSR spring return - With PST	1	1,35E-09	1,42E-08	0,00E+00	
M-torQ series MTDA Double acting - No PST	1	1,80E-08	0,00E+00	0,00E+00	
M-torQ series MTDA Double acting - With PST	1	1,61E-09	1,65E-08	0,00E+00	

Туре	A		
HFT	0		
Safety functions	Spring return actuators: 1. Delivery of a full stroke (90° ± tolerance) driven by the spring. With power fluid exhausted from the cylinder through the control system Double acting actuators: 1. Delivery of a full stroke (90° ± tolerance) driven by the piston of cylinder, powered by the specified medium working pressure.		
Mode of operation	Low Demand mode		

Systematic capability	3 (Route 1s applied)				
	Route 1 _H :	Applied	Route 2 _H :	Applied	
Architectural constraints	The product can be used in: Single channel configuration: Up to SIL 2 without external diagnostic tests Up to SIL 3 considering external diagnostic tests. Double channel configuration: up to SIL 3				
Remarks:	For further details, including environmental conditions, limitations of use, lifeline, failure rates traceability, mean repair times, common cause factors and systematic capability constraints, make reference to Safety Manual DOC.SILM.EF.EN.				

Issued at: Local HO

Ahmedabad, India

12.08.2023

S. Shivakumar

Place

Date

Head - Tech. Certification

H.O.(INDIA): Gulf Lloyds Industrial Services (INDIA) Pvt. Ltd.)
910, GALA Empire, Drive-in Road, Ahmedabad-380054, Gujarat, India.
info@gulflloyds.org; certification@gulflloyds.org
H.Q.(UAE): Gulf Lloyds (Middle-East) LLC
P.O. Box-30765, Electra Street Abu Dhabi, UAE; uae@gulflloyds.org;

www.gulflloyds.org

الخليج لويدز (الشرق الأوسط)

DOC. NO.:GL/TTC/009

Page 2 of 2

